

# SAFETY RECALL!



## Select Mustang Personal Flotation Devices (Containing Fluorescent Green Inflation Bladders)

West Marine SKU # / Manufacturer Part #	West Marine SKU # / Manufacturer Part #
10802601 / MD3183.CARB/BLK	14298624 / MD3183.VT3
10802619 / MD3183 LE BLK	14298632 / MD3184.WM Y/BLK
10802627 / MD3183 LE N/B	14298640 / MD3188
10802635 / MD3183 LE OL/B	16124513 / MD3183-02-RD/BK
10802643 / MD3183 LE OR/B	16124521 / MD3183-02-BK/SL
10929438 / MD3188	16124562 / MD3184-02-RD/BK
14298616 / MD3183.VLE N/BK	16124570 / MD3184-02-BK/SL

Mustang has discovered that some of the PFDs have an improper reinforcement of the bladder. If the bladder is torn, it will not provide any flotation protection if used which can result in serious injury or death.

Please inspect your product according to the instructions attached to this notice from Mustang Survival. If it is determined that your product is affected by this recall, please contact Mustang Survival at:

- 1-800-526-0532; or
- Email [productadvisories@mustangsurvival.com](mailto:productadvisories@mustangsurvival.com) to obtain specific return shipping instructions.

West Marine sincerely apologizes for the inconvenience of this product recall. We want to provide our customers with the safest boating experience possible, and always offer the most current information regarding the products we sell.